




Smoke and Dye-Water Observation Summary

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 120

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\120.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.

DYE TESTING FORM

Sketch (NTS)
Dye Test 120

MH 13AA2-012

Show North Arrow

CROSS COUNTRY BLVD.

SOUTH Rd.

Dye Flooded this
Catcg Basin
Defect A19

Dye Flooded this
Catch Basin
Defect A20

(A20)

RESULT CODES		SOURCE TYPE CODES		
1. POSITIVE	1. MAIN SEWER	5. DOWN SPOUT	9. STAIRWELL DRAI	13. STORM DRAIN
2. NEGATIVE	2. SERVICE LINE	6. DWN SPT CONN.	10. FOUNDATION DRAIN	14. CATCH BASIN
3. CANNOT TEST	3. TRANSITION JOIN	7. AREA DRAIN	11. BUILDING INTERIOR	15. STORM MH
	4. CLEAN OUT	8. DRIVEWAY DRAIN	12. MH FRAME/SEAL	16. STORM DITCH

Additional Comments: A20 - NO DYE SEEN IN SANITARY SEWER.

A19 NO DYE SEEN IN SANITARY SEWER.

1 A20

1 1